In this example, potentiometer values are read in through an 'Analog In' pin. The values are then used to control the position of a servo motor. Related examples:
http://arduino.cc/en/Tutorial/AnalogInput
http://arduino.cc/en/Tutorial/Knob

Made with Fritzing.org