
Carrier
PSYCHROMETRIC CHART
NORMAL TEMPERATURES
SI METRIC UNITS
Barometric Pressure 101,325 kPa
SEA LEVEL
Dry Bulb Temperature °C
Wet Bulb or Saturation Temperature °C
Enthalpy at saturation kJ/kg Dry Air
Relative Humidity
Enthalpy deviation kJ/kg dry air
Moisture content kg/kg Dry Air
Sensible Heat Factor
Below 0°C, Properties and Enthalpy Deviation Lines Are For Ice